

IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **SE/SP/QAR07.0002/13**

Page 1 of 2

QAR Free Ref. No.:

RISE File No.: P115955

Status:Issued

Details of change:

Re-assessment incl. assessment of change of address related to the strategic manufacturing supplier, Konprod. Additionally, it covers the assessment of competency documentation related to the new ex-responsible, Nina Truskog, whose new

Date of issue:2022-12-10
Valid until:2025-12-10

role becomes effective 2023-01-01.

Audit date:2022-09-27

Supplier previous name and address: Konprod AB, Örsätterfabriken, SE-597 91 Åtvidaberg, Sweden

Supplier current name and address: Konprod AB, Bruksgatan

9, SE-597 30 Åtvidaberg, Sweden

Site(s) audited:

INFICON AB

Wahlbecksgatan 25 SE-582 13 Linköping

Sweden

Issuing ExCB:

RISE - RISE Research Institutes of Sweden AB

Manufacturer:

INFICON AB

Wahlbecksgatan 25 SE-582 13 Linköping

Location of

Manufacturer:

Sweden

Product information:

Unchanged, refer to previous QAR: SE/SP/QAR07.0002/11...12

Protection concept:

Intrinsic safety "ia" (unchanged)

Related QARs:

 SE/SP/QAR07.0002/00
 SE/SP/QAR07.0002/01

 SE/SP/QAR07.0002/03
 SE/SP/QAR07.0002/04

 SE/SP/QAR07.0002/06
 SE/SP/QAR07.0002/07

 SE/SP/QAR07.0002/09
 SE/SP/QAR07.0002/10

 SE/SP/QAR07.0002/12
 SE/SP/QAR07.0002/10

SE/SP/QAR07.0002/02 SE/SP/QAR07.0002/05 SE/SP/QAR07.0002/08 SE/SP/QAR07.0002/11

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for previous versions:

 IECEx SP 07.0002X issue: 0
 IECEx SP 07.0002X issue: 1
 IECEx SP 07.0002X issue: 2

 IECEx SP 07.0002X issue: 3
 IECEx SP 07.0002X issue: 4
 IECEx SP 16.0001X issue: 0

 IECEx SP 16.0001X issue: 1
 IECEx SP 16.0001X issue: 2

Comments:

The assessment was completed on 2022-12-09, following an audit at INFICON's facility on 2022-09-27 and 2022-09-29 and an audit at the supplier's new facility, Konprod, on 2022-09-28; and an assessment of corrective actions.

Postal address for the audited manufacturer:

INFICON AB, Wahlbecksgatan 25, SE-582 13 Linköping, Sweden

Name and location of the audited supplier:

Konprod AB, Bruksgatan 9, SE-597 30 Åtvidaberg, Sweden

Note 1:



IECEx Quality Assessment Report Summary

QAR Ref. No.: SE/SP/QAR07.0002/13 Page 2 of 2

The assessment included auditing two new ATEX-ExTR and EC-Type of Examination certificates, listed below. However, since the parallel IECEx ExTR was not issued at the time of issuance of this QAR, no new CoC were issued. 1. Portable gas detector type IRwin SX*, according to report GB/BAS/ExTR22.0049/00 and EC-Type Exam. Baseefa16ATEX0034X/3 (2203149)

2. Portable hydrogen leak detector type Extrima (according to report R80094360A and EC-Type Exam. Sira 07ATEX2117X/8 (220202)

Note 2

SP Technical Research Institute of Sweden has renamed in 2017 to: RISE Research Institutes of Sweden AB